ICT KA SER

415/882-3000 Fax 415/882-3199

ICF Kaiser Engineers, Inc. 160 Spear Street. Suite 1380 San Francisco, CA 94105-1535

ENVIRONMENT & ENERGY GROUP

SFUND RECORDS CTR 0639-01854

1-800-744 2000 EPA Provisional ID TE'S CET / 860 753-9168

Montrose CAD 008242711

SFUND RECORDS CTR

88040535 0639-01854

MEMORANDUM

TO:

Nancy Woo, Remedial Project Manager

Enforcement Response Section (H-7-1)

· THROUGH:

Stewart Simpson, FASP Task Monitor

Laboratory Support Section (P-3-1)

FROM:

Daniel P. Rodoni, Environmental Geologist

Environmental Services Assistance Team (ESAT)

DATE:

November 7, 1994

SUBJECT:

Residual Materials from the 1994 Soil Investigation near the

Montrose Chemical Corporation Superfund Site in Southern Los

Angeles County, California

An October 25, 1994 ESAT memorandum to EPA regarding the subject residual materials included a request for signature on a Waste Profile Sheet (WPS). stated in the October 25 memorandum, USPCI was selected by Stewart Simpson to transport and incinerate the subject residual materials. Prior to characterization, removal, transportation, and incineration of the waste, USPCI requires that a WPS be completed and signed by the waste generator. The October 25 memorandum included photocopies of two completed WPSs as attachments. Although signatures on the photocopies of these WPSs are satisfactory for USPCI, it is requested that signatures be provided on the original WPSs. Please sign and return the attached original WPSs as soon as possible.

The WPSs are not manifests for the transport and disposal of the waste, but documents which describe the waste and identify the party responsible for the waste. A manifest will be required to be signed by EPA prior to the removal of the waste. It will not be necessary for an EPA representative to be present at the Montrose site to sign the manifest. The manifest may be signed and sent via facsimile or mail to USPCI prior to the removal of the waste. The manifest will be provided to EPA for signature once the waste has been characterized by USPCI.

If you have any questions or comments please call Dan Rodoni at (415) 882-3043.

Attachments: two



Waste Profile Sheet

FOR ASSISTANCE, PLEASE CONTACT:

Lone Mountain Facility Route 2, Box 170 Waynoka, Oklahoma 73860 Customer Service405/697-3500 Grassy/Grayback Mountain Facility P.O. Box 22750 Salt Lake City, Utah 84122-9998 3 miles east, 7 miles north of exit 41 off I-80 Grassy Mountain Facility, Utah 84029 Customer Service801/595-3900 **Clive Incineration Facility** P.O. Box 22285 Salt Lake City, Utah 84122-1285 3.5 miles south of milepost 49 off I-80 Clive, Utah 84029 *Customer Service*801/595-44001-800-CLIVE UT

Analytical Services 4322 South 49th West Avenue Tulsa, Oklahoma 74107 Customer Service
Treatment and Recovery Services, Tulsa 5324 W. 46th Street South Tulsa, Oklahoma 74107 Customer Service
Treatment and Recovery Services, Wichita 2549 N. New York Street Wichita, Kansas 67219 Customer Service
Treatment and Recovery Services, San Antonio 4303 Profit Drive San Antonio. Texas 78219 Customer Service
Treatment and Recovery Services, San Jose 1040 Commercial Street, Suite 109

USPCI Customer Service Center1-800-877-2416

NOTICE

All USPCI customers must complete this Waste Profile before USPCI can accept a Waste Stream for management. Federal and state laws require USPCI to obtain certain information from our customers to assure that wastes are managed in compliance with applicable regulations.

Please fill out this form completely, making sure to answer each question. Include supplemental waste analyses or process information when requested or when necessary to help USPCI determine appropriate management practices for your waste. An incomplete profile, or one containing inaccurate information, will unnecessarily delay the waste acceptance process and may result in violations of hazardous waste management regulations.

A revised Waste Profile Sheet must be submitted if 1) the waste's chemical or physical properties change, 2) the process generating the waste changes, or 3) changes in applicable regulations alter the regulatory status of the waste or any constituents.

Please ship the top (original) copy of this form, a Representative Sample* (collected in accordance with EPA publication SW-846) of the waste stream and chain-of-custody documentation, if required (contact the USPCI facility to which this form is submitted to determine chain-of-custody requirements), to the designated USPCI facility. Retain the backcopy of this form for your records.

* Some waste streams may not require a representative sample.

San Jose, California 95112

V	V	as	te	P	ro	fil	е	Sh	ee	1
---	---	----	----	---	----	-----	---	----	----	---

A Subsidiary of Union Pacific Corporation	□ Sta	indard Approval	□ RUSH	l Approval (extra ch	harge) V	Vaste	Profil	e Sł	166.
FOR USPCI USE ONLY Exhibit A to	Contract date	Sample reference	#	PO #		Sales Represe			
IMPORTANT INFORMATION NE	EDED BEFOR	RE COMPLET	ING TH	IIS FORM:		<u> </u>			
All boxes MUST be complete Incomplete Profiles will result your facility customer service When a check-off box is used Leaving the box blank indicate.	ed unless otherw t in unnecessary representative of d on this form, pl	rise indicated. delays. Please or USPCI sales lease check the	supply a represe box if th	all required inforr ntative. ne item describes		•	•		
. Generator Information				,					·
Generator Company Name LS ENVIRONMENTAL Prot Generator Facility Address EPA SITO TRAJER! MONTROS 1059 West 20th Stre So. LOS ANGELES GO. TORMNCE, CA Generator Mailing Address: USEPA REGION 9 LABORA RICHMOND FIRID STATION RICHMOND CA 94809 ATTN: STEWART SIMPS INVOICE DIRECTIONS DAN ROCIONI ICLE KAISER ENGINEERS 160 SPEAR ST STE 1380 SAND FIRNCISCO, CA 9410 I. Waste Generation Information	e superfun et et et et et et et et et et et et et	x Site	X State X State Facili Phone Phone Phone Phone Phone Phone Technics Phone Phone Phone Tif spe	5-749 -244 nical Contact/Title (ge tewar + Se (c -4/2-233 or, Contractor, Invoice) AN Roclan	erator) Rem O 4 enerator) Simpson BS Contact/Title Di Es Ted, please sp	Fax 5/0-	-744-1	199 199	1/
Waste name		.~					· · · · · · · · · · · · · · · · · · ·		
Describe process producing waste (attach addition Sampling) Estimated rate of waste generation Is the waste generated from a Is the waste generated by a chemical Does this waste contain benzene sub If "Yes" please specify the benzene contains the sampling of the sa	RCRA corrective Il manufacturing rject to the control	e action ☑ CEI plant, coke by-pol requirements	☐ Pound RCLA sit	recovery plant or	urce 🗆 n a petroleu	hly □ Quarte none of the p none refinery?	oreceding .	Ď No	me only
II. Waste Constituents, Characterist	ics and Propert	ties			,				
Physical state Solid Liquid Powder Contains free liquids? yes no Waste Composition Octoris Judgax, put		iume LOX % Range in % 99-100 7c	□ biod sort □ nor sort	contains: (check onl degradable bents n-biodegradable bents pestos	☐ cyanie☐ conta ☐ conta	des-level_ minated soi minated s (per EPA)	l □ oxidi □ PCB □ stron	s-level	·
limited to PPE gioves bags chution tape, sheeting, pipets p	plastic plastic apen towels		au ex	oroperties: (check of topolymerizable plosive drophoric	nly if applica ☐ infe ☐ pyrd	ible)	☐ reactive☐ shock s☐ thermal	ensitive	
clisposable Laborator		0-190	_ Bulk d	al properties density fic gravity ality			Jari Point <u>72</u>	in.	
Total must equa	l at least 100%	·	pH rang	je □ 2.1-5 □ 5.1	1-8 🗆 8.1	1-12.4 □ ≥	12.5	, 1	Range
Complete for Thermal Destruction (if applicable of Heat Value (BTU/lb) to to to to	☐ Vap	al Bromine	mHG)	_ @ STP _ @°F _ to%	☐ Total ☐ Total ☐ Total ☐ Total ☐ Total	Fluoride lodine		to tò to to	% % %
V. Special Handling, Safety or Other	Additional Info	ormation	-						
						•			

Signature
REV AUG 1993

Printed name

Date



Waste Profile Sheet

FOR ASSISTANCE, PLEASE CONTACT:

Lone Mountain Facility Route 2, Box 170 Waynoka, Oklahoma 73860 Grassy/Grayback Mountain Facility P.O. Box 22750 Salt Lake City, Utah 84122-9998 3 miles east, 7 miles north of exit 41 off I-80 Grassy Mountain Facility, Utah 84029 Customer Service801/595-3900 Clive Incineration Facility P.O. Box 22285 Salt Lake City, Utah 84122-1285 3.5 miles south of milepost 49 off I-80 Clive, Utah 84029 Customer Service801/595-4400

Analytical Services	
4322 South 49th West Avenue	
Tulsa, Oklahoma 74107	
Customer Service	918/446-1162
Treatment and Recovery Services,	Tulsa
5324 W. 46th Street South	
Tulsa, Oklahoma 74107	
Customer Service	918/445-2171
Treatment and Recovery Services,	Wichita
2549 N. New York Street	
Wichita, Kansas 67219	•
Customer Service	316/268-7500
·	
Treatment and Recovery Services,	San Antonio
4303 Profit Drive	
San Antonio, Texas 78219	
Customer Service	210/304-3000
Treatment and Recovery Services,	San Jose
1040 Commercial Street, Suite 109	
San Jose California 95112	
Customer Service	408/451-5000
Choronia. Donoto initia	

USPCI Customer Service Center1-800-877-2416

NOTICE

All USPCI customers must complete this Waste Profile before USPCI can accept a Waste Stream for management. Federal and state laws require USPCI to obtain certain information from our customers to assure that wastes are managed in compliance with applicable regulations.

Please fill out this form completely, making sure to answer each question. Include supplemental waste analyses or process information when requested or when necessary to help USPCI determine appropriate management practices for your waste. An incomplete profile, or one containing inaccurate information, will unnecessarily delay the waste acceptance process and may result in violations of hazardous waste management regulations.

A revised Waste Profile Sheet must be submitted if 1) the waste's chemical or physical properties change. 2) the process generating the waste changes, or 3) changes in applicable regulations alter the regulatory status of the waste or any constituents.

Please ship the top (original) copy of this form, a Representative Sample* (collected in accordance with EPA publication SW-846) of the waste stream and chain-of-custody documentation, if required (contact the USPCI facility to which this form is submitted to determine chain-of-custody requirements), to the designated USPCI facility. Retain the back copy of this form for your records.

* Some waste streams may not require a representative sample.



☐ Standard Approval ☐ RUSH Approval (extra charge) Waste Profile Sheet

OR USPCI USE ONLY xhibit A to	Contract date	Sample reference #	PO#	Sale	es Representative 人のAPR	
1 All boxes MUST be complete 2. Incomplete Profiles will resure your facility customer service 3. When a check-off box is use Leaving the box blank indicates.	ed unless otherw It in unnecessary e representative of d on this form, pl	ise indicated. delays. Please s or USPCI sales r ease check the t	supply all required information in the supply all required information in the supply and supply all required in the supply all re		ı have questions, pl	
Generator Information				·		·
enerator Company Name U.5_EN VIRONMEN*A2	Protection	. Agency	X C A D C	10 18	12 1412	M / /
enerator Facility Address EPA 3 te Trailer, Mon	trose Supers		State Generator ID			<u> </u>
1059 West 2014 Str Sc. LOS ANGELES Co, TONN			Facility Contact/Title (gene NAWCY Woo	Remadi	al Project M	'C,1
enerator Mailing Address:. U.S.E.P.A. Region 9 habor	*Atory		415 - 744 - à	7404	Fax 415-744	-1717
enerator Mailing Address: U.S.EPA REGION 9 NADO RICH MOND FICKI STATIO 1337 S. 46 th St. Bu.	INDINC 201		Technical Contact/Title (ge	enerator)	FASP TASK	Marton
RICHMONICA, CA 74804	-	/1.55%	5/6-4/2-23 Broker. Contractor, Invoice	Contact/Title	510-4/2-2	304
ATTN: STEWART Sim,		12-23.33	Phone Rodow	ESAT	Geologist	
DAR ROCIONI .			1 Specific treatment is desi	13	415-882-	3159
TOF KAISER ENGINEER 160 SPEAR St. STE 15 SAN FRANCISCO CA 94111	780 x=-)421=		INCINERATE		Standard Industry Code	(SIC)
Waste Generation Information	<i>3 1305</i>					
aste name Pesi dual Sa escribe process producing waste (attach addition	meline Wi	44er				
JAMPLING		()				
stimated rate of waste generation	Units D	rums 🗆 Gallons [☐ Pounds ☐ Tons ☐ Yard	Frequency In Monthly	☐ Quarterly ☐ Yearly	/ Ine time only
s the waste generated from a	RCRA corrective	action	CLA site	urce 🗆 none	e of the preceding	
s the waste generated by a chemical Does this waste contain benzene sub f "Yes" please specify the benzene contains the benzene contain	ject to the contro	I requirements of	oduct recovery plant or f 40 CFR Part 61 Subp	a petroleum i art FF (NESH	refinery?	IZ No No
. Waste Constituents, Characterist		·				
nysical state I Solid ☑ Liquid □ Powder ontains free liquids? ☑ yes □ no		ume <u>/H/</u> %	Waste contains: (check onl ☐ biodegradable sorbents ☐ non-biodegradable	y if applicable) Q eyanides C contamin C contamin	nated soil avid	ing acids dizers 3s-level
Waste Composition Waste Composition		9970010	sorbents □ asbestos	debris (p	er ÉPA) 🔲 stro	ng odor ides-level
2.4-00=			Waste properties: (check of autopolymerizable			:
2.4'-000 2.4' 00T		218	explosive hydrophoric	☐ pyreph	oric 🗆 shock	
			Physical properties		. /	iny serisitive
			Specific gravity		Color / Varia	200
			Normality			
mplete for Thermal Destruction (if applicable Heat Value (BTU/lb) to Water Content (%) to Ash (%)	e) □ Vapo □ Visc	or Pressure (mm	□ ≤ 2 □ 2.1-5 √ 5. HG) @ STP °F	☐ Total Chle ☐ Total Fluc ☐ Total lodi	orine oride ne	Rangeto% _to% _to%
Special Handling, Safety or Other	<u> </u>		to%	☐ Total Sulf	fur	to%
			<u> </u>		· · · · · · · · · · · · · · · · · · ·	